



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

ENGINEERING CHANGE REQUEST

ECR 105

Date Opened:	11/17/20 10:50 AM	Requested By:	Larocque, Eric
Type:	Drawing/Pattern Change	Responsible Engineer:	Drouin, Steven
Priority:	Medium	Requester*:	Larocque, Eric
Status:	Under Review	DE Approver*:	Shepherd, David
Reason:		ECR Lead*:	Drouin, Steven
Expense:	0	DM:	Seib, Victoria
Target Date:			
Execution Date:			
ECR Approval No:			
RE (R&D):		**BRIEF DESCRIPTION**:	wearplate issue
Status Note:		DESCRIPTION/ ADR CONTENT**:	front clamp issue on D5735-047 Clamp is to big ussing model DT10788

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
D5735-047		On hold	FWD Wearplate Assembly, LH	Finished Good			
D5735-048		On hold	FWD Wearplate Assembly, RH	Finished Good			

INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
D5735-047		0 Quarantine	0 *	2 Update Jobs only when drawing approved
D5735-048		0 Quarantine	0 *	2 Update Jobs only when drawing approved

EFFECTS

Effect Group	Effects
1. Quarantine?	Immediate quarantine required
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required (-047/-048)
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review
4. Production Type	In-house production
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors (Wrong clamp used on -47/-048)
7. Final Impacts	Parts Must Comply (must use -3 clamp for -47/-048)
9. Sustaining Cost Grouping	Poor Quality